



STATE OF NEVADA  
DIVISION OF MINERALS  
DISSOLVED MINERAL RESOURCE EXPLORATION  
BOREHOLE OR WELL DRILLER'S PLUGGING REPORT  
*Please complete this form in its entirety in accordance with NAC 534B*

Report: PW0007  
For Division Use Only

Borehole:   
Well:

**PRINT OR TYPE IN BLACK INK ONLY  
DO NOT WRITE ON BACK**

1. OPERATOR Pilot Peak LLC BOREHOLE OR WELL NAME: LUN22-01  
MAILING ADDRESS: 1225 15th Street NW PROJECT NAME: Columbus Basin  
Washington D. C. 20005 FEDERAL - BLM NV# 101126  
COUNTY: \_\_\_\_\_

2. LOCATION NE 1/4 of the SE 1/4, Sec 27 T 3 N S, R 36 E 3. NDOM Perm/NOI Number  
Latitude \_\_\_\_\_ or UTM E 418.630  NAD83  
Longitude \_\_\_\_\_ UTM N 4.215.770  WGS84 W0010

4. EXISTING BOREHOLE OR WELL CONSTRUCTION  
Depth Drilled 2,182 Feet Depth Cased 100 Feet (well only)

5. WATER LEVEL  
Static water level 20 feet below land surface  
 Artesian Flow N/A G.P.M. N/A P.S.I.  
Water Temperature 70 °F

6. BOREHOLE/WELL PLUGGING MATERIALS

| Material Used | From | To   | Feet    | Feet | Feet | Pumped                              | Poured                              |
|---------------|------|------|---------|------|------|-------------------------------------|-------------------------------------|
| Neat Cement   | 0    | 50   | feet to | feet | feet | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| Bore Grout    | 50   | 2182 | feet to | feet | feet | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| Material Used | From | to   | feet to | feet | feet | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| Material Used | From | to   | feet to | feet | feet | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| Material Used | From | to   | feet to | feet | feet | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| Material Used | From | to   | feet to | feet | feet | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |

Neat Cement Fluid Weight lbs/gal 15.4  
Bentonite Grout 20 % bentonite

NEXT SECTION TO BE COMPLETED IN CASE OF WELL PLUGGING ONLY - FOR BOREHOLES SKIP TO SECTION 8

7. WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth please explain why:  
\_\_\_\_\_  
\_\_\_\_\_  
Was the casing pulled?  yes  no If pulled, from: \_\_\_\_\_ feet to \_\_\_\_\_ feet  
Was the casing over drilled?  yes  no

EXISTING CASING SCHEDULE

| Material Used | Size O.D.     | WhPt        | Wall Thickness | From     | To         |
|---------------|---------------|-------------|----------------|----------|------------|
| Steel         | 5.5" (Inches) | 72 (Pounds) | .244 (Inches)  | 0 (Feet) | 100 (Feet) |
|               | (Inches)      | (Pounds)    | (Inches)       | (Feet)   | (Feet)     |
|               | (Inches)      | (Pounds)    | (Inches)       | (Feet)   | (Feet)     |

Existing Perforations:  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet From \_\_\_\_\_ feet to \_\_\_\_\_ feet

8. Additional Notes or Comments  
PWT casing was cemented in place with an excess of 2" annulus from 0-100' with neat cement. HWT casing dropped below surface. 1400 HWT casing was not recovered. Numerous attempts to fish HWT casing was made with no success in finding it due to hole washed out in excess of 12" in diameter hole below PWT casing per caliper log readings. Estimated depth of HWT casing in hole is 120'-1520'. HRQ rods twisted off at 1502', fishing out was unsuccessful. HRQ rods left in hole from 1502'-2132'. 2-HQ barrel, tube and latchhead assemblies lost in hole between 1840'-2182'.

9. Date Started 5/16/22 Date Completed 5/18/22

10. DRILLER'S CERTIFICATION  
This borehole or well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Premier Drilling Co. Contractor  
Address 2021 Meadow Ridge Drive, Elko, NV 89801 Contractor  
Phone 775-934-3858  
Nevada contractor's license number issued by the State Contractor's Board 0081008  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2039  
Signed Dennis F. ... by driller performing actual plugging on site  
Date 5/20/22