



STATE OF NEVADA
DIVISION OF MINERALS
DISSOLVED MINERAL RESOURCE EXPLORATION
BOREHOLE OR WELL DRILLER'S PLUGGING REPORT
Please complete this form in its entirety in
accordance with NAC 534B

Report#:
For Division Use Only

Borehole
Well

PRINT OR TYPE IN BLACK INK ONLY
DO NOT WRITE ON BACK

1 OPERATOR Sierra Lithium
MAILING ADDRESS 4754 Caughlin Parkway
Reno, NV 89519
COUNTY Esmaralda

BOREHOLE OR WELL NAME MBD 01
PROJECT NAME Clayton Valley - 143 North
FEDERAL BLM NVN# N95763 NMC#1138212

2 LOCATION NW 1/4 of the NE 1/4 Sec. 28 T. 01 N. R. 39 E.
Latitude 37.828 of NAD83
Longitude -117.654 of NAD83
3 NDCM Permit No. Number _____
W0000 _____

4 EXISTING BOREHOLE OR WELL CONSTRUCTION
Depth Drilled 1318 Feet Depth Cased 390 Feet (well only)

5 WATER LEVEL
Static water level 220 feet below land surface
Artesian Flow N/A G.P.M. N/A PSI
Water Temperature N/A °F

6 BOREHOLE/WELL PLUGGING MATERIALS

Material Used	From	feet to	feet	feet	Pumped <input type="checkbox"/>	Poured <input type="checkbox"/>
Abandonite	1316	900	900	900	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Abandonite	900	500	500	500	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Abandonite	500	50	50	50	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Cement	50	0	0	0	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
_____	_____	_____	_____	_____	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
_____	_____	_____	_____	_____	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Neat Cement Fluid Weight lbs/cgal 15.0pg
Bentonite Grout 20 % bentonite

NEXT SECTION TO BE COMPLETED IN CASE OF WELL PLUGGING ONLY - FOR BOREHOLES SKIP TO SECTION 8

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth please explain why _____

~~RWT (5.5) Casing was cemented in at start of hole. RWT casing was left in hole at completion 0 to 54~~
~~HWT (4.5) Casing was reamed down to 390 during drilling of the hole. Casing was stuck in the hole at 390' casing was cut and 340' was recovered~~

Was the casing pulled? yes no if pulled, from 340 feet to 0 feet
Was the casing over drilled? yes no

EXISTING CASING SCHEDULE

Material Used	Size O D	WWT	Wail Thickness	From	To
steel	4.5 (Inches)	11.7 (Pounds)	25 (Inches)	0 (Feet)	390 (Feet)
steel	5.5 (Inches)	14.4 (Pounds)	25 (Inches)	0 (Feet)	50 (Feet)
_____	_____ (Inches)	_____ (Pounds)	_____ (Inches)	_____ (Feet)	_____ (Feet)

Existing Perforations:
From _____ feet to _____ feet From _____ feet to _____ feet
From _____ feet to _____ feet From _____ feet to _____ feet
From _____ feet to _____ feet From _____ feet to _____ feet

8 Additional Notes or Comments

~~RWT Casing casing was cemented from bottom to surface with neat cement 15.3 ppg. Hole was abandoned from TD to surface~~

9 Date Started 4-25-18 Date Completed 5-14-18

10 DRILLER'S CERTIFICATION

This borehole or well was plugged and abandoned under my supervision and the report is true to the best of my knowledge

Name Bart Longyear Company Contractor

Address 2455 South 3600 West, West Valley City UT 84119 Contractor

Phone 385-234-3854

Nevada contractor's license number issued by the State Contractor's Board 10157

Nevada driller's license number issued by the Division of Water Resources, the on site driller 1793

Signed _____

by driller performing actual plugging on site

Date 6-13-18