



STATE OF NEVADA
DIVISION OF MINERALS
DISSOLVED MINERAL RESOURCE EXPLORATION
BOREHOLE OR WELL DRILLER'S PLUGGING REPORT
Please complete this form in its entirety in
accordance with NAC 534B

Report#: _____
For Division Use Only

Borehole:
Well:

PRINT OR TYPE IN BLACK INK ONLY
DO NOT WRITE ON BACK

1. OPERATOR American Lithium Corp.
MAILING ADDRESS 1507-1030 West Georgia St.
Vancouver B.C. V6E 2Y3
COUNTY Esmeralda

BOREHOLE OR WELL NAME: ALC-18-02
PROJECT NAME: American Lithium Fishlake
FEDERAL - BLM NVN# 094885

2. LOCATION SE 1/4 of the SE 1/4, Sec 25 T 1 N S R 36 E
Latitude _____ or UTM E 408964 NAD83
Longitude _____ or UTM N 4186245 WGS84

3. NDOM Permit/NOI Number
NO005

4. Depth Drilled 2342 Feet EXISTING BOREHOLE OR WELL CONSTRUCTION
Depth Cased 980 Feet (well only)

5. WATER LEVEL
Static water level 12" feet below land surface
Artesian Flow 10 G.P.M. < 8 P.S.I.
Water Temperature 80 °F

6. BOREHOLE/WELL PLUGGING MATERIALS

| Material Used | From | feet to | feet | <input checked="" type="checkbox"/> Pumped | <input checked="" type="checkbox"/> Poured |
|----------------------------------|-----------------------|---------|------|--------------------------------------------|--------------------------------------------|
| Neat Cement | 420 | feet to | 0 | <input checked="" type="checkbox"/> Pumped | <input checked="" type="checkbox"/> Poured |
| Aberrantite | 920 | feet to | 420 | <input checked="" type="checkbox"/> Pumped | <input checked="" type="checkbox"/> Poured |
| Neat Cement | 1030 | feet to | 920 | <input checked="" type="checkbox"/> Pumped | <input checked="" type="checkbox"/> Poured |
| Aberrantite | 2342 | feet to | 1030 | <input checked="" type="checkbox"/> Pumped | <input checked="" type="checkbox"/> Poured |
| Neat Cement Fluid Weight lbs/gal | <u>15.5</u> | | | | |
| Bentonite Grout | <u>20</u> % bentonite | | | | |

NEXT SECTION TO BE COMPLETED IN CASE OF WELL PLUGGING ONLY - FOR BOREHOLES SKIP TO SECTION 8

7. WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth please explain why:

Was the casing pulled? yes no
Was the casing over drilled? yes no
If pulled, from: 370 feet to 0 feet

EXISTING CASING SCHEDULE

| Material Used | Size O.D. | Wt/Ft | Wall Thickness | From | To |
|---------------|---------------------|----------------------|---------------------|-----------------|-------------------|
| <u>HWT</u> | <u>4.5</u> (Inches) | <u>11.7</u> (Pounds) | <u>.25</u> (Inches) | <u>0</u> (Feet) | <u>980</u> (Feet) |
| _____ | _____ (Inches) | _____ (Pounds) | _____ (Inches) | _____ (Feet) | _____ (Feet) |
| _____ | _____ (Inches) | _____ (Pounds) | _____ (Inches) | _____ (Feet) | _____ (Feet) |

Existing Perforations:
From _____ feet to _____ feet From _____ feet to _____ feet
From _____ feet to _____ feet From _____ feet to _____ feet

8. Additional Notes or Comments
Casing was stuck in hole and could not pull.

9. Date Started 8-3-18 Date Completed 8-23-18

10. DRILLER'S CERTIFICATION

This borehole or well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Boart Longyear Co.
Address 2455 ~~500~~ 3600 W West Valley City, UT 84119
Phone 385 234 3854
Nevada contractor's license number issued by the State Contractor's Board 10157
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2594
Signed Michael Jey
Date 10/2/18 by driller performing actual plugging on site

RECEIVED
OCT 04 2018
DIVISION OF MINERALS