

RECEIVED

JAN 10 2020



STATE OF NEVADA
DIVISION OF MINERALS
DISSOLVED MINERAL RESOURCE EXPLORATION
BOREHOLE OR WELL DRILLER'S PLUGGING REPORT

Report#:
For Division Use Only

Borehole: [checked]
Well: []

PRINT OR TYPE IN BLACK INK ONLY
DO NOT WRITE ON BACK

1. OPERATOR ft cady corporation
MAILING ADDRESS 16195 siskiyou rd, 210
COUNTY apple valley ca, 92307
churchill

BOREHOLE OR WELL NAME: ap-02 BMA
PROJECT NAME: salt wells
FEDERAL - BLM NVN# 98585

2. LOCATION se 1/4 of the ne 1/4, Sec 24 T 17 N S, R 30 E
Latitude or UTM E 365512 NAD83
Longitude or UTM N 4354101 WGS84
3. NDOM Permit/NOI Number n0010 N0010

4. Depth Drilled 708 Feet
EXISTING BOREHOLE OR WELL CONSTRUCTION
Depth Cased Feet (well only)

5. WATER LEVEL
Static water level 10 to 0 feet below land surface
Artesian Flow yes 25 G.P.M. 10 P.S.I.
Water Temperature 70 °F

6. BOREHOLE/WELL PLUGGING MATERIALS
Material Used boregrout/cement From 708 feet to 205 feet [checked] Pumped [checked] Poured
Material Used portland neat cem From 205 feet to surface feet [checked] Pumped [checked] Poured
Material Used From feet to feet [checked] Pumped [checked] Poured
Material Used From feet to feet [checked] Pumped [checked] Poured
Material Used From feet to feet [checked] Pumped [checked] Poured
Material Used From feet to feet [checked] Pumped [checked] Poured
Neat Cement Fluid Weight lbs/gal 15 lbs
Bentonite Grout 20 plus 10.5 % bentonite

NEXT SECTION TO BE COMPLETED IN CASE OF WELL PLUGGING ONLY - FOR BOREHOLES SKIP TO SECTION 8

7. WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? [checked] yes [] no
If well was not cleaned out to total depth please explain why:

Was the casing pulled? [checked] yes [] no
Was the casing over drilled? [checked] yes [] no
If pulled, from: feet to feet

Table with columns: Material Used, Size O.D., Wt/Ft, Wall Thickness, From, To. Rows for existing casing schedule.

Existing Perforations:
From feet to feet
From feet to feet
From feet to feet

8. Additional Notes or Comments
Artesian flow was present during drilling and increased below 500 feet when second sand layer encountered. We utilized a method with bore grout and cement in combination to control the flow and plug the well when completed that worked very well. Playa became virtually impossible to travel on toward the end of the hole. Note: hole was cored + rock bitted

9. Date Started 11/14/2019 Date Completed 12/21/2019

DRILLER'S CERTIFICATION

This borehole or well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name: Patrick Harris Harris Exploration Drilling Contractor
Address: p.o. box 5579 Fallon Nevada 89407 Contractor
Phone: 760-822-7886 Contractor
Nevada contractor's license number issued by the State Contractor's Board: 00260010A
Nevada driller's license number issued by the Division of Water Resources, the on-site driller: 2554
Signed: Patrick M. Harris Rick Lewis On site
Date: 1-10-2020 by driller performing actual plugging on site