



STATE OF NEVADA  
DIVISION OF MINERALS  
**DISSOLVED MINERAL RESOURCE EXPLORATION**  
**BOREHOLE OR WELL DRILLER'S PLUGGING REPORT**  
*Please complete this form in its entirety in accordance with NAC 534B*

Report#: PB0005  
For Division Use Only

Borehole:   
Well:

**PRINT OR TYPE IN BLACK INK ONLY**  
**DO NOT WRITE ON BACK**

1. OPERATOR belmont nevada incorporated BOREHOLE OR WELL NAME: kb 6  
MAILING ADDRESS 1212 south casing blvd. PROJECT NAME: kibby basin  
las vegas nevada 89104 FEDERAL - BLM NVN# 094992  
COUNTY esmeralda

2. LOCATION ne 1/4 of the se 1/4, Sec 30 T 6  N  S, R 37.5 E  
Latitude \_\_\_\_\_ or UTM E 431300  NAD83  
Longitude \_\_\_\_\_ UTM N 4244630  WGS84

3. NDOM Permit/NOI Number  
N0006

4. EXISTING BOREHOLE OR WELL CONSTRUCTION  
Depth Drilled 620 Feet Depth Cased pulled out Feet (*well only*)

5. WATER LEVEL  
Static water level 15 feet feet below land surface  
Artesian Flow no G.P.M. \_\_\_\_\_ P.S.I.  
Water Temperature unknown °F

6. BOREHOLE/WELL PLUGGING MATERIALS

Material Used <u>abandonite</u>	From <u>20</u>	feet to	<u>620</u>	feet	<input checked="" type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
Material Used <u>cement</u>	From <u>surface</u>	feet to	<u>20</u>	feet	<input checked="" type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
Material Used _____	From _____	feet to	_____	feet	<input checked="" type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
Material Used _____	From _____	feet to	_____	feet	<input checked="" type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
Material Used _____	From _____	feet to	_____	feet	<input checked="" type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
Material Used _____	From _____	feet to	_____	feet	<input checked="" type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured

Neat Cement Fluid Weight lbs/gal 7  
Bentonite Grout 20 % bentonite

**NEXT SECTION TO BE COMPLETED IN CASE OF WELL PLUGGING ONLY - FOR BOREHOLES SKIP TO SECTION 8**

7. WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth please explain why:  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
Was the casing pulled?  yes  no If pulled, from: \_\_\_\_\_ feet to \_\_\_\_\_ feet  
Was the casing over drilled?  yes  no

EXISTING CASING SCHEDULE

Material Used	Size O.D.	Wt/Ft	Wall Thickness	From	To
_____	_____ (Inches)	_____ (Pounds)	_____ (Inches)	_____ (Feet)	_____ (Feet)
_____	_____ (Inches)	_____ (Pounds)	_____ (Inches)	_____ (Feet)	_____ (Feet)
_____	_____ (Inches)	_____ (Pounds)	_____ (Inches)	_____ (Feet)	_____ (Feet)

Existing Perforations:  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet From \_\_\_\_\_ feet to \_\_\_\_\_ feet

8. Additional Notes or Comments  
encountered some salt brine and lost circulation from surface to 120 feet, very thick clay, continued in clay and intervals of sand and gravel to depth. No big changes in water intrusion or lithology. We could not get back on the playa for several months to complete testing and abandonment due to water on surface made playa impassable.

9. Date Started november 30, 2018 Date Completed april 4, 2019

10. DRILLER'S CERTIFICATION  
This borehole or well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name harris exploration drilling Contractor  
Address p.o. box 5570 fallon nevada Contractor  
Phone 7608227886  
Nevada contractor's license number issued by the State Contractor's Board 0026000a  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2554  
Signed [Signature] by driller performing actual plugging on site  
Date 8-4-2019