



STATE OF NEVADA  
DIVISION OF MINERALS  
DISSOLVED MINERAL RESOURCE EXPLORATION  
BOREHOLE OR WELL DRILLER'S PLUGGING REPORT  
*Please complete this form in its entirety in accordance with NAC 534B*

Report#: PB0060  
For Division Use Only

Borehole:   
Well:

PRINT OR TYPE IN BLACK INK ONLY  
DO NOT WRITE ON BACK

1. OPERATOR Rangefront Mining Services BOREHOLE OR WELL NAME: RCV-08  
MAILING ADDRESS 1031 Railroad Street Suite 102B PROJECT NAME: Goat Flat  
Elko, NV 89801 FEDERAL - BLM NVN#: NVNV10638621  
COUNTY Esmeralda

2. LOCATION 1/4 of the 1/4, Sec T  N  S R E 3. NDOM Permit/NOI Number  
Latitude 446039.57 UTM E  NAD83  
Longitude 4182938 UTM N  WGS84  
NV0126

4. EXISTING BOREHOLE OR WELL CONSTRUCTION  
Depth Drilled 1120 Feet Depth Cased \_\_\_\_\_ Feet (well only)

5. WATER LEVEL  
Static water level 140 feet below land surface  
Artesian Flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water Temperature 76.1 °F

6. BOREHOLE/WELL PLUGGING MATERIALS

Material Used	<u>Cement</u>	From	<u>0</u>	feet to	<u>20</u>	feet	<input checked="" type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
Material Used	<u>Bore Hole Grout</u>	From	<u>20</u>	feet to	<u>1360</u>	feet	<input checked="" type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
Material Used	_____	From	_____	feet to	_____	feet	<input checked="" type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
Material Used	_____	From	_____	feet to	_____	feet	<input checked="" type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
Material Used	_____	From	_____	feet to	_____	feet	<input checked="" type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
Material Used	_____	From	_____	feet to	_____	feet	<input checked="" type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
Neat Cement Fluid Weight lbs/gal	_____							
Bentonite Grout	_____	% bentonite						

NEXT SECTION TO BE COMPLETED IN CASE OF WELL PLUGGING ONLY - FOR BOREHOLES SKIP TO SECTION 8

7. WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth please explain why:  
\_\_\_\_\_  
\_\_\_\_\_

Was the casing pulled?  yes  no If pulled, from: \_\_\_\_\_ feet to \_\_\_\_\_ feet  
Was the casing over drilled?  yes  no

EXISTING CASING SCHEDULE

Material Used	Size O.D.	Wt/Ft	Wall Thickness	From	To
_____	_____ (Inches)	_____ (Pounds)	_____ (Inches)	_____ (Feet)	_____ (Feet)
_____	_____ (Inches)	_____ (Pounds)	_____ (Inches)	_____ (Feet)	_____ (Feet)
_____	_____ (Inches)	_____ (Pounds)	_____ (Inches)	_____ (Feet)	_____ (Feet)

Existing Perforations:  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet From \_\_\_\_\_ feet to \_\_\_\_\_ feet

8. Additional Notes or Comments  
78 Bags of grout, 10 bags of cement all pumped downhole  
\_\_\_\_\_  
\_\_\_\_\_

9. Date Started 10/10/24 Date Completed 10/13/24

10. DRILLER'S CERTIFICATION  
This borehole or well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Relando Regalado, Envirotech Drilling Contractor  
Address 900E 4th Street, Winnemucca, Nevada 89445 Contractor  
Phone 775-421-0481  
Nevada contractor's license number issued by the State Contractor's Board 0075392  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2384  
Signed Relando Regalado by driller performing actual plugging on site  
Date 10/14/2024